

Mini BMW Mini - Lighting up of the engine warning light | HELLA

Mini

BMW Mini: R50/ R52/ R53

All models with the W10 / W11 engine code

Model year: 2002–2006

Air locks in the cooling system.

Lighting up of the engine warning light.

If the coolant temperature gauge fluctuates and/or the engine warning light comes on in the above-mentioned vehicles, a possible cause could be the presence of air locks in the cooling system or in the coolant circulation system. In such cases it is also possible that the P0128 fault code is stored.

The P0128 fault code refers to the following malfunction: coolant thermostat, coolant temperature below the thermostat regulating temperature.

We recommend using a radiator vacuum filling device to get rid of the source of the problem and/ or to optimise the ventilation of the coolant circulation system.

For example:

- 8PE 185103-271 Hella Nussbaum Solutions