



Citroën C3 - left fog lamp permanently on

Data sheet

Manufacturer

Citroën

Vehicle model

C3

Engine

All models

Year of manufacture

From 2016

Symptoms

Fog lamp permanently on

Important safety note

Left fog lamp always on in Citroën C3

On the vehicles mentioned above, the left fog lamp may light up permanently. Error code A98F (error left fog lamp) is stored in the multifunction control unit.

The cause may be a fault in the fuse box (relay plate 1) in the engine compartment.

The following steps should be taken to rectify the problem:

- Switch off the ignition
- Wait 10 minutes
- Disconnect the battery's ground cable
- Disconnect the middle 28-PIN multi-plug in the fuse box
- Connect the battery's ground cable
- Switch on the ignition

If the fog lamp no longer lights up, there is a defect within the fuse box. To restore the correct function, the fuse box should be replaced.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.