

Citroen C2 / C3 - Failure of the front light | HELLA

Citroen

C2 / C3 / C3 Puriel

Model year: 10/2006 – 03/2008

Failure of the front light

The complaint has been made that the front headlight fails in the above vehicles.

The above problem with the lighting system may be caused by faulty ECU software.

The light switch position may not be detected by the ECU and thus leads to a failure of the front lighting.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

To remedy the above problem, the software needs to be updated at the relevant vehicles by a specialist workshop.