

# **Fiat Ducato - Power loss / Engine warning light illuminates | HELLA**

**Fiat**

**Ducato**

**Model years: 01/2015 - 01/2018**

**Engine: Multijet**

## **Power loss / Engine warning light illuminates**

In above vehicle, the fitting of the intercooler might disconnect from connecting body.

This results in a significant engine power loss and the engine indicator lamp will light up.

To remedy the situation, check the respective fixing of the fitting and replace the holding clamp against a modified version.

The vehicle manufacturer has already addressed the issue and notified the owners of the affected models. Due to various reasons, we must assume that not all vehicles have undergone the retrofitting/ modification.