

# Jeep Commander - Recirculation air flap malfunction | HELLA

Jeep

Commander

Model year: 2006

With manual air-conditioning system

Recirculation air flap malfunction

Flashing AC button

With the above vehicles the function indicator of the AC button (Figure) may suddenly start flashing at higher speeds. In addition, the recirculation air flap is repeatedly opened and closed, often noticeable by a squeaking noise.

In this case the fault should not be sought in the recirculation air system, but the flap control. Replacement of the control unit (Figure) can often rectify the problem.



