

Mazda 5 - Noise coming from the centre air nozzles in the dashboard area | HELLA

Mazda

Mazda 5

Model year: 2010 to 2012

Noise coming from the centre air nozzles in the dashboard area

With the above-mentioned vehicles, noises/vibrations can occur in the centre air nozzles in the dashboard area when the heating/air conditioning system is switched on. This effect is amplified at high speed.

This is caused by a construction-related malfunction in the dashboard centre air nozzle for the heating and air conditioning system.

The vehicle manufacturer has already recognised the problem and is offering a modified dashboard centre air nozzle (see table).

Spare parts (SP)