Mitsubishi/Fuso Canter - Oil cooler hose | HELLA

Mitsubishi/Fuso

Canter TF/TF1

Model year: 2011-09-16 - 2014-12-17

Oil cooler hose

On the above vehicles, the oil cooler hoses on the fully automatic direct shift transmission (Duonic transmission) must be checked and, if necessary, replaced. If this is not done, there is a risk of the hoses bursting and oil escaping.

Further information can be obtained from the

vehicle manufacturer. When contacting the manufacturer, provide the operation reference code: RC1502