

# Peugeot 807 - Condensation water outflow | HELLA

**Peugeot**

**807**

**Year of manufacture: 2002 - 2005**

**Condensation water outflow /**

**Problem**

The airbag monitoring lamp lights up. In an extreme case, the airbag(s) is/are activated.

**Possible causes**

- In case of accumulation of water in the footwell: Defective outflow of condensation water from the air conditioner.
- If the airbag monitoring lamp lights up: Water in the airbag control device.

**Remedy**

- Check and clean out the condensation water outflow; check the airbag control device for entry of water.
- Obtain further information on remedies from the auto manufacturer.