



Subaru XV - booming noises from the rear of the vehicle

Data sheet	
Manufacturer	Subaru
Vehicle model	XV
Year of manufacture	From 2017 onwards
Engine	All models
Symptoms	Booming noises from the rear of the vehicle

Important safety note

Subaru XV - booming noises from the rear of the vehicle

If loud, booming noises are heard from the rear of the vehicle, defective rear wheel bearings may be the cause.

The rear wheel bearings may have been damaged by a design-related malfunction of the rear wheel brakes during assembly.

In order to remedy this, not only new wheel hubs but also modified backing plates (picture) for the rear brake have to be installed.

When assembling, please observe the vehicle manufacturer's specifications.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.