

Volvo S40 - Stop light not functioning | HELLA

Volvo

Volvo S40

Model year: up until 2004

Stop light not functioning

If the above-mentioned vehicle is found to have a functional failure of the stop light to the left/right, this may be caused by a defect in the central electronic control unit/module (CEM).

Repair notes

- Check light sources
- Check fuse 11B/13
- Possible malfunctioning plug connections (loose) and/or contact problems (corroded) could cause contact issues.
- Check switch function / relay function by means of the central electronic control unit/module (CEM).

Remedy:

- If necessary, replace the central electronic control unit/module (CEM).