



Volvo S60 Water ingress in cars with sunroof

Data sheet

Manufacturer

Volvo

Vehicle model

S60

Year of manufacture

2010 - 2018

Symptoms

Water ingress on vehicles with sunroof

Important safety note

Volvo S60 - water ingress in vehicles with an adjustable or sliding sunroof

Vehicles with an adjustable or sliding sunroof are affected. When the sunroof is opened, water can penetrate into the vehicle interior.

The cause could be dirt deposits in the area of the sunroof wind deflector.

In such a case, it is recommended, as a preventive measure, to clean this area thoroughly and to keep it free of new dirt deposits on a regular basis.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.