



VW Golf 7 - unable to open fuel filler flap

Data sheet

Manufacturer

VW

Vehicle model

Golf 7

Year of manufacture

2012 - 2017

Symptoms

Fuel filler flap does not open


Important safety note

Fuel filler flap is difficult to open or does not open

If the fuel filler flap in the above-mentioned vehicles does not open or only opens sporadically, there are various potential causes:

Tip:

A fuel filler flap that does not open can usually be re-opened by lightly tapping on the left side of the lid and simultaneously locking and unlocking it again using the remote control.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the

document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.