



BMW 1 Series - vehicle vibrations and noises from the engine compartment

Data sheet	
Manufacturer	BMW
Vehicle model	1 Series (F40)
Engine	All models
Year of manufacture	2019 - 31 October 2020
Symptoms	Vehicle vibrations

Important safety note

Vibrations and noises in different driving situations

The vehicles mentioned above may vibrate and make noise when accelerating, braking or starting. The knocking sounds are perceived as coming from the engine compartment.

The cause could be a defect in the upper right engine mount (engine suspension).

In order to rule out other causes, the engine, wheel and transmission suspension and other components (which could trigger the noise) should be inspected and checked before replacing the engine mount.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.