

# **BMW 7 Series - Front and rear axle brake system squeals**

**BMW**

**7 Series E 65/66**

**All models**

**Model year 2001–2008**

## **Front and rear axle brake system squeals when applying light braking force**

If the above fault occurs, it may be associated with the brake lining wear indicator. When applying light braking force, the thermal contact on the brake disk may drag, thereby causing an unpleasant squeal. In this case, the thermal contacts must be checked and, if required, replaced with the new versions.

OE part number: front thermal contact 34356778037

rear thermal contact 34356778038

## **HELLA spare part numbers**

Brake lining thermal contact, front axle:

Brake lining thermal contact, rear axle:

## **Repair note**

In this case, it is advisable to check the brake disks and brake linings for wear and, if necessary, replace them.