

# Mercedes Benz M-Class - Irregular engine running | HELLA

**Mercedes Benz**

**M-Class (163)**

**Model year: 1999 – 2004**

**Engine: 612,963**

**All models**

**Irregular engine running**

Error code: P1187

Common rail pressure is too high/low

If the above fault code is read in the fault memory of this vehicle model's ECU, this may be associated with a defect in the fuel filter. Air inclusions in the fuel line after the filter can lead to a lack of fuel flow.

In this case, the fuel supply should be checked and the fuel filter should be replaced if necessary.

The vehicle manufacturer offers a modified fuel filter in the spare parts program.

Spare part number:

Fuel filter A 611 092 00 01

Fuel filter (bio diesel) A 611 092 00 01

Afterwards clear the fault memory entry using a diagnostic instrument.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.