



# Nissan Navara (D40) - Power loss and error code P0093

|                     |                               |
|---------------------|-------------------------------|
| Data sheet          |                               |
| Manufacturer        | Nissan                        |
| Vehicle model       | Navara (D40)                  |
| Year of manufacture | 2010 - 2016                   |
| Symptoms            | Power loss   Error code P0093 |

## Important safety note

## Loss of power and an additional stored error code P0093 on the Nissan Navara may be caused by the following

A loss of engine power and rough idling in the vehicles mentioned above may be caused by defective injection valves. An additional stored error code P0093 indicates that there is a pressure drop in the fuel system.

The following steps should be taken to rectify the problem:

- Check fuel lines and fuel filters and replace if necessary
- Check fuel pressure, pressure regulator and injector nozzles using a diagnostic device
- Inspect the catalytic converter for damage caused by unburnt fuel
- Replace defective components
- Clear fault memory

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the

document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.