

Opel Astra H - Air conditioning not working in automatic mode | HELLA

Opel

Astra H

Model years: 2004 - 2008

With electronic climate control (ECC)

Air conditioning not working in automatic mode

In the above vehicles, "software failure" may be the cause that the air conditioning works only in manual mode. The display will then often show an incomprehensible error message (M1 - M5).

This can be remedied by a software update.

The vehicle manufacturer has already been using the modified software at the factory starting from the following VINs:

W0L0AHL4882160266 - (Bochum plant)

W0L0AHL0885117742 - (Antwerp plant)

W0L0AHL4888096223 - (Ellesmere Port plant)