

Opel Astra J - Alternator control light illuminates | HELLA

Opel

Astra J

Model year: 2010 - 2012

Fault code B1517

On the above mentioned vehicles the alternator control light may illuminate even though the battery voltage and alternator voltage are correct. At the same time the fault code B1517 (03) is saved in the control unit. This code signifies "Battery voltage below nominal value".

A "software bug-" may be the cause of this problem.

The control unit may react excessively "sensitively". In case of a customer complaint, the battery and alternator should be checked. If no faults are found, the software can be updated to rectify the problem.