

# Opel Insignia - Engine warning light comes on | HELLA

Opel

Insignia

Model year: 2010 - 2011

Engine warning light comes on

**Error code: C1221, C1222, C1223, C1224**

These mean that the input signal of the speed sensors is 0.

If the error codes can be linked with the above-mentioned problem, this could point to faulty control unit software.

According to the vehicle manufacturer, the situation can be remedied by programming the engine control unit with revised and improved software.

Such updating of software is only to be carried out by an authorised dealer.