

Opel Insignia - Poor engine performance / Final speed is not achieved | HELLA

Opel

Insignia

Model years: 2011 - 2012

With engine: A28NER / A28NET

With automatic transmission: AF40

Poor engine performance / Final speed is not achieved

In the above vehicles, an improperly tuned engine software may be the cause they are not able to reach their final speed. The customer may also complain about the performance of the engine.

The affected vehicles are those having VINs starting at: B1000001

The vehicle manufacturer is already aware of the problem and is providing modified software as a remedy.

The new software has been used at the factory in new vehicles since February 2012.

If you are experiencing these problems, please contact an Opel dealership.