

# **Peugeot 307, 308, Expert - Lighting failure | HELLA**

**Peugeot**

**307, 308, Expert**

**Model year: Nov. 2006 - Dec. 2008**

## **Lighting failure**

The vehicles mentioned above may experience a lighting failure despite the light being switched on.

The actuation of the switch by the control unit is not detected, so the lighting remains switched off.

This problem can be resolved by performing a software update at the authorized garage.

The vehicle manufacturer has already launched a recall campaign to deal with the problem. For various reasons, however, it must be assumed that not all vehicles have been modified.