



Suzuki Swift (A2L) - ESP makes noises when car starts off

Data sheet	
Manufacturer	Suzuki
Vehicle model	Swift (A2L)
Year of manufacture	2017 - all models without Emergency Brake Assist
Symptoms	ESP makes noises when car starts off

Important safety note

When the car starts off, noise may be generated by the ESP hydro unit on the Suzuki Swift

With the above-mentioned vehicle, noise may be generated by the ESP hydraulic unit when this car starts off. A software weakness could be a possible cause of the problem.

In order to find a remedy, all other possible causes of malfunction should first be ruled out by means of mechanical and electrical system tests. It is also advisable to read out the error memory. If no errors are identified, an update of the ESP control unit should be carried out. Getting in touch with a manufacturer's authorised workshop is always an advantage in such cases.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.