



Toyota Yaris - check-engine light and error code P0011

Data sheet	
Manufacturer	Toyota
Vehicle model	Yaris
Engine	1.0 i (1KR-FE)
Year of manufacture	up to 2015
Symptoms	Check-engine light Error code: P0011

Important safety note

Check-engine light comes on Error code P0011

If the check-engine light comes on in the vehicles mentioned above and the error code P0011 (camshaft timing) is stored in the control unit, a defective camshaft timer may be the cause. The design may mean that the camshaft timer's vent hole becomes blocked. The timer should be replaced to solve the issue. Contacting an authorised Toyota dealership is advisable.

This may also be of interest to you

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.