



Volkswagen e-Golf 7 - Rear window washer fluid keeps running

Data sheet	
Manufacturer	Volkswagen
Vehicle model	e-Golf VII
Engine	All models with rear window wiper system
Year of manufacture	up to 2015
Symptoms	Rear window: Washer fluid keeps running

Important safety note

Washer fluid does not stop running

The following problem is observed on the vehicles mentioned above. The rear window wiper system has been operated and washer fluid keeps running from the nozzle after the spraying process. A defective washer nozzle on the rear window wiper system was identified as the cause. Please proceed as follows to rectify the problem: Replace the defective washer nozzle with a washer nozzle with a non-return valve in accordance with the manufacturer's specifications. Next, a functional check should be performed to check that the repair measure has worked.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.