



## VW Golf 7 - wiper failure (windscreen)

Data sheet	
Manufacturer	VW
Vehicle model	Golf 7
Engine	All
Year of manufacture	2012 - 2017
Symptoms	Windscreen wiper motor failure

### Important safety note

## Windscreen wipers do not work

If the windscreen wipers fail, the fuse should be checked first. If it is not defective, the recommendation is reading out the error memory using a diagnostic device. If an error code is stored there in connection with the wiper motor, the cause could be a communication error between the wiper motor and the multifunction control unit. If this is the case, disconnecting the battery for 10 minutes can remedy the problem. After connecting the battery, all error memory entries should be cleared. In many cases, the wiper motor works again. Check whether a software update is available from the vehicle manufacturer to permanently remedy the problem.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.