



Opel Vectra B model year 1996-1997 Fuel gauge displays incorrectly

Fuel gauge shows only 50 liters despite the tank being full.

If the complaint is as above the fault could be due to a sticking fuel lever sensor, this is caused by the lever float jamming on the supply cable.

If this is the case then the float unit must be removed and the supply cable re-routed so that it does not foul the float unit.

Bulletin