



## **Alfa Romeo 147 all models**

### **False fuel tank display**

If the vehicle is filled with fuel when the ignition is switched on, this can lead to the fuel tank level being displayed incorrectly. The reason for this is the system control for the tank sensor. In this case this is not caused by a technical defect which can be eliminated by replacing a certain component.

This instruction is not included in the vehicle manual but is being added by the manufacturer. If the problem occurs please inform your customers about this special feature that the vehicle may only be filled with fuel with the ignition switched off.

