



Audi

A4 (8D, B5)

Model year: up to 01/1999

Engine: AHL

Noise development at the front right

If gurgling and/or bubbling noises should occur in the front right-hand area of the vehicle, this can be connected to the ventilation hose of the activated carbon canister. The ventilation hose, which is routed downwards to the vehicle undercarriage and then into the fresh air, has a bend. Condensation can collect in this bend. During operation, the noises described above can occur during fresh air intake. To eliminate the problem, remove the wheel housing panel on the front right. Drill a 3 mm hole into the now visible hose at the lowest point of the bend, so that the water collected can drain out of the hose.