



Daewoo Nubira (J190) ***Model year: 1999-2001***

Danger of short circuit at the battery cable

In the case of the above-mentioned vehicles, the battery cable harness can chafe against the clip for the radiator hose and cause a short circuit. The cable harness should be examined for chafing and re-insulated if necessary. The cable harness must be laid and fixed in such a way that it is impossible for it to touch the radiator hose clip. The hose clip must be turned round if necessary.