



Mercedes Benz E-Class (W210) All models

Low washer-fluid control lamp illuminates.

If there are complaints with these vehicles that the control lamp for the window-washer system shows that the washer-fluid level is low, even though the washer-fluid level in the tank is sufficient, one possible cause is a defective switch for the washer-fluid level display. Cracks in the housing allow water to penetrate the switch and damage it. In order to eliminate the fault, the switch should be checked and, if necessary, replaced.



Washer-fluid level switch