



Mini **Model year from 12.2001 to 03.2004** **All vehicles with seat heating**

Seat heating does not work correctly

If there are complaints above the above-mentioned fault, the cause could be an incorrect heating element resistance. In this case, the customer may complain about excessively strong or weak warming from the seat heating. For both cases, special adapter harnesses (see Fig. 1, Item 1), which are inserted into the existing seat wiring harness (see Fig. 1, Item 2), are offered by the manufacturer. After installation, these are then fastened to the seat frame with the aid of cable clips (see Fig. 2, Item 3).

Fig. 1




Fig. 2

