



Bulletin

Opel

Mokka

Model year: 2013

Vehicle Identification Number: DB000001 – BD033498

GPS not functioning

The GPS symbol is crossed out when shown in the display. There may be incorrect country allocation during navigation.

If the above error messages are displayed, this may be due to incorrect connection of the cable to the aerial base.

The aerial base in the affected vehicles is replaced with a correctly wired base in the specialist workshop.

The vehicle manufacturer has already addressed the issue. The manufacturer states that correctly wired antenna bases are being used in production from Vehicle Identification Number: WOLJC7EL2DB033498.