



## Peugeot 806 All models with HDI diesel engine

### Engine has no power or does not start.

If there are complaints with these vehicles that the engine has no power or does not start, one possible cause is a vacuum in the fuel tank. Due to this, the engine cannot be supplied with sufficient fuel. In order to eliminate the fault, a new ventilation line (Fig. 1) must be installed for the tank. The ventilation line can be obtained via the Peugeot sales network.

#### Note

If there is a plug (Fig. 2) at the end of the new line that is to be connected to the T-piece, this plug be removed and disposed of.




Fig. 1




Fig. 2