



Saab 9-3

All models from 1998–2003

Vehicle locks/unlocks of its own accord, engine cannot be started.

If there are complaints with these vehicles that the doors lock or unlock of their own accord and that the engine cannot be started, one possible cause is a trapped cable on the front door handle. The door handle on the driver side and the passenger side may be affected. In order to eliminate the fault, the door-handle holder must be removed and the cable connection checked. If a damaged cable is found, depending on the damage, the cable can be repaired. If the damage is too great, the entire door handle with the connected cables should be replaced.

Bulletin

