



MCC Smart Smart City, Cabrio, Fortwo Model year 1998 – 2003 with 40 KW engine

Battery run down.

If there are complaints with these vehicles that the battery runs down, one possible cause is the instrument panel. For fault diagnosis, the type description and quiescent current consumption of the instrument panel must be checked. If the instrument panel has the type description V016 – V019 and the quiescent current measured is greater than 50 mA, the instrument panel has to be replaced.