



VW Lupo **All models**

The radio switches off by itself.

If there are complaints with these vehicles that the radio switches off by itself, one possible cause is a software fault.

This affects the radio models Beta 5 made by Phillips.

In certain operational conditions the radio can switch off by itself, but it can be switched on again by pressing the on/off button.

To eliminate the fault the radio has to be initialised again. To do this, remove the radio and disconnect the voltage supply plug for at least 10 seconds.