



## ***Ford Mondeo Turnier build from 9/2001 With rigid trailer coupling and park distance control***

### **Permanent sound of the park distance control when the reverse gear is engaged.**

If, on this vehicle with original Ford rigid trailer coupling, a permanent sound of the park distance control occurs when the reverse gear is engaged, the cause is a software fault in the control unit of the park distance control. The ultra sonic sensors in the rear bumper sense the ball hitch of the trailer coupling when the reverse gear is engaged. To rectify the problem the control unit, fitted behind the left side panel in the trunk, must be renewed. For this consider the following steps:

- Remove the cargo bay cover
- Remove the trunk door seal in the D-pillar area.
- Remove the D-pillar panel.
- Open the left side panel and remove the bracket of the first aid kit.
- Remove the left side panel
- Lift up the carpeting and remove the two screws and the three plugs of the park distance control unit.
- Remove the old control unit and refit the new one.
- Refit all the parts in reverse order.
- Check the function.