## Bulletin



© Hella KGaA Hueck & Co., Lippstadt 10. September 2001 1-1

## VW from 2/1999

## CD changer

An updated CD changer as original equipment is being installed in the above-mentioned vehicles as from February 1999. These devices can only read "burned" CD's if they were burnt in the file format "Audio".

A check with an "original" CD can prove whether the CD changer is functioning.

This should also be taken into consideration as the fault cause when this occurs in other vehicle-/system manufacturers.



