



Daewoo Nubira Model year: 1997 - 1999

ABS - warning lamp illuminates

In the case of the above-mentioned vehicles it can occur that the ABS warning light goes on and off when the hand brake is applied. A fault code is not stored in the fault memory. In this case the ground point in the upper area of the left-hand A-pillar must be checked after the pillar trim has been removed. If necessary, residual paint must be removed from this spot in order to create perfect ground cable contact. The cleaned ground connection should then be treated with a suitable corrosion protection agent.