



Opel
Meriva B
Model year: 2010 - 2012
With radio-CD/CDC 300+400

Direction indicators and parking aid
Delayed playback of
sounds

On the above mentioned vehicles, the playback of the warning, direction indicating sounds and the sounds for the parking aid may be delayed due to a software bug.

If the audio function operates with a certain delay, modified software may rectify the problem. Contact one of the vehicle manufacturer's dealers on this issue.

Only vehicles equipped with a radio-CD or CDC of the type 300 and 400 are affected.