



Seat Alhambra **From model year 1999** **1.9 TDI PD with engine code ANU**

Engine misfires

With the Seat Alhambra 1.9 TDI unit injector with the engine code ANU, the engine can misfire or run out-of-round, including loss of power.

When the fault memory is read out, the fault codes 18074 – 18077 are shown, which indicates an electrical problem at the injectors.

The plug-type connections at the injectors should be checked first.

The 5-pole plug connection is near the injectors. One of the connections can have become loose within this plug connection.

The problem is remedied by inserting the connection correctly and securing it again.

Then the fault memory can be deleted and the engine started up.

Further part replacement is not necessary in this case.