



Volvo C 70

Model year 1997 to 2005

Poor engine running

If there are complaints from customers about the above-mentioned fault, the cause could be residues in the throttle housing. Owing to these residues, the throttle cannot close perfectly and the engine runs roughly. In this case, proceed as follows:

- Remove the throttle housing.
- Clean off the residues/deposits from the inner wall using a suitable cleaner. Ensure that all residues are removed completely. After this, purge the housing using compressed air.
- After cleaning, operate the throttle manually approximately 5 times until the stop is reached, in order to check for perfect function.
- After this, refit the throttle housing.
- Carry out a test drive in order to test the driving properties.

Bulletin