



## **VW Beetle**

### **Model year 1998**

### **Vehicle identification number from**

### **3BW -000 001 to 3BW -999 999**

#### **Airbag control lamp is permanently lit.**

If there are complaints with these vehicles that the airbag control lamp is permanently lit, this could be caused by a faulty airbag control unit and faulty sensors for the side airbags. Faulty side airbag sensors can lead to destruction of the airbag control unit. The following fault entry is stored in the fault memory: "9 faults recognised – cannot be deleted – function is unknown or cannot be carried out at the moment." To eliminate the fault the side airbag sensors and the airbag control unit have to be replaced.