



Opel Astra G All Models as of Model Year 1999

Noises From Area of Interior Lamp

If complaints are received on these vehicles that noises can be heard from the area of the interior lamp, the interior lamp may be the cause. Too much play between the mounting opening and mounting hooks on the interior lamp allow it to rattle against the handle. To eliminate this rattling, proceed as follows:

- Remove interior lamps.
- Cut off an approx. 3 mm long piece of windshield washer hose.
- Slide the piece of hose over the mounting hooks on the interior lamp.
- Install interior lamp and check whether it is tight.

