

Fiat Idea Lancia Musa - Sporadic illumination of hazard blinking lights | HELLA

Fiat Idea

From VIN 122376 to 129997

Lancia Musa

From VIN 1050002-1057835

All vehicles with manual temperature control

Sporadic illumination of hazard blinking lights

If a customer complains about the above problem, this could be caused by the hazard light switch. Due to an internal defect in the switch, the hazard blinking lights are activated without being deliberately switched on. In this case, the hazard light switch must be replaced.

Proceed as follows.

