



Dacia Duster - noises when starting/starter following

Data sheet	
Manufacturer	Dacia
Vehicle model	Duster (HJD)
Engine	All models
Year of manufacture	2017- 2021
Symptoms	Noises when starting/starter following

Important safety note

Noises when starting

When starting the engine on the vehicles mentioned above, noise may be caused by the starter running with the engine. There is a risk of destroying the starter.

A defective ignition lock may be causing the problem.

In addition, the starter and wiring harness, as well as the electrical connections, should be checked for mechanical and electrical damage. If necessary, these must be repaired or renewed.

To remedy this, replace the ignition lock with a modified version.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.