

# **Honda CR-V III - Malfunction of Air conditioning system | HELLA**

**Honda**

**CR-V III**

**Model year: from 2007**

**Engine: 2.2 CTDi**

## **Air conditioning system is temporarily not functioning**

The air conditioning system may malfunction temporarily due to a defective relay.

The failure of the air conditioning system is noticeable by sporadic "overheating" of the vehicle interior.

To fix this problem, check the compressor relay in the relay/fuse box of the engine compartment (fig.) and replace it if necessary.

