

Opel Meriva B - Delayed playback of sounds | HELLA

Opel

Meriva B

Model year: 2010 - 2012

With radio-CD/CDC 300+400

On the above mentioned vehicles, the playback of the warning, direction indicating sounds and the sounds for the parking aid may be delayed due to a software bug.

If the audio function operates with a certain delay, modified software may rectify the problem. Contact one of the vehicle manufacturer's dealers on this issue.

Only vehicles equipped with a radio-CD or CDC

of the type 300 and 400 are affected.