



Porsche Cayenne: Error code: 16864/P0480 and vehicle does not start

Data sheet	
Manufacturer	Porsche
Vehicle model	Cayenne
Engine	4.5L V8 M48/00 and M48/50/S
Year of manufacture	2003 to 2007
Symptom	Error code: 16864/P0480 - "Radiator fan control 1, electrical fault" Vehicle does not start Battery has had deep discharge

Important safety note

Porsche Cayenne: Error code: 16864/P0480 - "Radiator fan control 1, electrical error"

If the above defect is detected, it may be related to a defective radiator fan module. Only affects vehicles with two fan motors (dual fan module).

The cause here is contamination in the control unit, which leads to automatic switching on and off and unusually long running times for the electric fan motors.

According to the vehicle manufacturer, the complete dual fan module must be replaced. Charge and check the vehicle battery and replace it if necessary. Delete error memory entries.

 **IMPORTANT**

In this regard, please always follow the repair information from the vehicle manufacturer.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.