



## *Fiat Brava/Bravo*

### Premature activation of the crash-sensor

On the above-mentioned vehicles a premature firing of the crash-sensor can occur (sometimes due to fast closing of the doors). This leads then to an interruption of the fuel supply. To overcome the problem, it is enough to reset the switch under the driver's seat. For better access the seat should be pushed fully back to the stop.

